Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Aquatic Life Use

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Dissolved Oxygen grab average	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146	8	0	
Dissolved Oxygen grab average	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120	9	2	
Dissolved Oxygen grab average	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120	9	0	
Dissolved Oxygen grab average	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120	71	3	
Dissolved Oxygen grab average	No Concern	Middle portion of reservoir, East Pointblank	5,120	18	1	
Dissolved Oxygen grab average	No Concern	Middle portion of reservoir, centering on US 190	5,120	24	1	
Dissolved Oxygen grab average	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	20	1	
Dissolved Oxygen grab average	No Concern	Riverine portion of reservoir, centering on SH 21	324	56	0	
Dissolved Oxygen grab average	No Concern	Upper portion of reservoir, centering on SH 19	2,799	60	3	
Dissolved Oxygen grab average	No Concern	Upper portion of reservoir, west of Carlisle	4,841	23	0	
Dissolved Oxygen grab average	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675	8		

Dissolved Oxygen grab minimum	No Concern-Limited Data	Cove off upper portion of reservoir, East Trinity	4,146	8	0	
Dissolved Oxygen grab minimum	No Concern	Lower portion of reservoir, East Willow Springs	5,120	9	0	
Dissolved Oxygen grab minimum	No Concern-Limited Data	Lower portion of reservoir, East Wolf Creek	5,120	9	0	
Dissolved Oxygen grab minimum	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	71	2	
Dissolved Oxygen grab minimum	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120	18	0	
Dissolved Oxygen grab minimum	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	24	0	
Dissolved Oxygen grab minimum	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	20	0	
Dissolved Oxygen grab minimum	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	56	0	
Dissolved Oxygen grab minimum	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	60	0	
Dissolved Oxygen grab minimum	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	23	0	
Dissolved Oxygen grab minimum	No Concern-Limited Data	West Carolina Creek cove, off upper portion of reservoir	675	8	0	

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Aquatic Life Use (continued)

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Dissolved Oxygen 24hr average	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146	0		
Dissolved Oxygen 24hr average	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120	0		
Dissolved Oxygen 24hr average	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120	0		
Dissolved Oxygen 24hr average	Not Assessed	Lowermost portion of reservoir, adjacent to dam	5,120	0		
Dissolved Oxygen 24hr average	Not Assessed	Middle portion of reservoir, East Pointblank	5,120	0		
Dissolved Oxygen 24hr average	Not Assessed	Middle portion of reservoir, centering on US 190	5,120	0		
Dissolved Oxygen 24hr average	Not Assessed	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	0		
Dissolved Oxygen 24hr average	Not Assessed	Riverine portion of reservoir, centering on SH 21	324	0		
Dissolved Oxygen 24hr average	Not Assessed	Upper portion of reservoir, centering on SH 19	2,799	0		
Dissolved Oxygen 24hr average	Not Assessed	Upper portion of reservoir, west of Carlisle	4,841	0		
Dissolved Oxygen 24hr average	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Lowermost portion of reservoir, adjacent to dam	5,120	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Middle portion of reservoir, East Pointblank	5,120	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Middle portion of reservoir, centering on US 190	5,120	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Riverine portion of reservoir, centering on SH 21	324	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Upper portion of reservoir, centering on SH 19	2,799	0		
Dissolved Oxygen 24hr minimum	Not Assessed	Upper portion of reservoir, west of Carlisle	4,841	0		
Dissolved Oxygen 24hr minimum	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675	0		

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Aquatic Life Use (continued)

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Acute Metals in water	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	36	0	
Acute Metals in water	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	13	0	
Acute Metals in water	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	10	0	
Acute Metals in water	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	35	0	
Acute Metals in water	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	35	0	
Acute Metals in water	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	13	0	
Chronic Metals in water	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	36		
Chronic Metals in water	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	13		
Chronic Metals in water	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	10		
Chronic Metals in water	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	35		
Chronic Metals in water	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	35		
Chronic Metals in water	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	13		
Overall Aquatic Life Use	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Aquatic Life Use	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120			
Overall Aquatic Life Use	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Aquatic Life Use	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Aquatic Life Use	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120			
Overall Aquatic Life Use	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120			
Overall Aquatic Life Use	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall Aquatic Life Use	Not Assessed	Remainder of reservoir	39,095			
Overall Aquatic Life Use	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324			
Overall Aquatic Life Use	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799			
Overall Aquatic Life Use	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Aquatic Life Use (continued)						
Overall Aquatic Life Use	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675			
Contact Recreation Use						
E. coli single sample	Not Assessed	Lowermost portion of reservoir, adjacent to dam	5,120	0		
E. coli single sample	Not Assessed	Middle portion of reservoir, centering on US 190	5,120	0		
E. coli single sample	Not Assessed	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	0		
E. coli single sample	Not Assessed	Riverine portion of reservoir, centering on SH 21	324	0		
E. coli single sample	Not Assessed	Upper portion of reservoir, centering on SH 19	2,799	0		
E. coli single sample	Not Assessed	Upper portion of reservoir, west of Carlisle	4,841	0		
E. coli geometric mean	Not Assessed	Lowermost portion of reservoir, adjacent to dam	5,120	0		
E. coli geometric mean	Not Assessed	Middle portion of reservoir, centering on US 190	5,120	0		
E. coli geometric mean	Not Assessed	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	0		
E. coli geometric mean	Not Assessed	Riverine portion of reservoir, centering on SH 21	324	0		
E. coli geometric mean	Not Assessed	Upper portion of reservoir, centering on SH 19	2,799	0		
E. coli geometric mean	Not Assessed	Upper portion of reservoir, west of Carlisle	4,841	0		
Fecal coliform single sample	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	51	0	
Fecal coliform single sample	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	15	0	
Fecal coliform single sample	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	11	0	
Fecal coliform single sample	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	57	11	
Fecal coliform single sample	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	57	5	
Fecal coliform single sample	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	15	1	
Fecal coliform geometric mean	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	51		6

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Contact Recreation Use (continued)						
Fecal coliform geometric mean	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	15		9
Fecal coliform geometric mean	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	11		22
Fecal coliform geometric mean	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	57		122
Fecal coliform geometric mean	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	57		34
Fecal coliform geometric mean	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	15		24
Overall Recreation Use	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Recreation Use	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120			
Overall Recreation Use	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Recreation Use	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Recreation Use	Not Assessed	Middle portion of reservoir, East Pointblank	5,120			
Overall Recreation Use	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120			
Overall Recreation Use	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall Recreation Use	Not Assessed	Remainder of reservoir	39,095			
Overall Recreation Use	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324			
Overall Recreation Use	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799			
Overall Recreation Use	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841			
Overall Recreation Use	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675			
General Use						
Water Temperature	No Concern-Limited Data	Cove off upper portion of reservoir, East Trinity	4,146	8	0	
Water Temperature	No Concern-Limited Data	Lower portion of reservoir, East Willow Springs	5,120	9	0	
Water Temperature	No Concern-Limited Data	Lower portion of reservoir, East Wolf Creek	5,120	9	0	
Water Temperature	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	72	0	
Water Temperature	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120	18	0	

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
General Use (continued)						
Water Temperature	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	24	0	
Water Temperature	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	20	0	
Water Temperature	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	58	0	
Water Temperature	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	65	1	
Water Temperature	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	24	1	
Water Temperature	No Concern-Limited Data	West Carolina Creek cove, off upper portion of reservoir	675	8	0	
pH	Use Concern-Limited Data	Cove off upper portion of reservoir, East Trinity	4,146	8	3	
pH	No Concern-Limited Data	Lower portion of reservoir, East Willow Springs	5,120	9	0	
pH	No Concern-Limited Data	Lower portion of reservoir, East Wolf Creek	5,120	9	0	
pH	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	66	1	
pH	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120	18	0	
pH	Use Concern	Middle portion of reservoir, centering on US 190	5,120	23	3	
pH	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	20	2	
pH	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	58	2	
pH	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	64	6	
pH	Partially Supporting	Upper portion of reservoir, west of Carlisle	4,841	24	5	
pH	Use Concern-Limited Data	West Carolina Creek cove, off upper portion of reservoir	675	8	2	
Chloride	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146	239		36.6
Chloride	Fully Supporting	Lower portion of reservoir, East Willow Springs	5,120	239		36.6
Chloride	Fully Supporting	Lower portion of reservoir, East Wolf Creek	5,120	239		36.6
Chloride	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	239		36.6
Chloride	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120	239		36.6

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
General Use (continued)						
Chloride	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	239		36.6
Chloride	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	239		36.6
Chloride	Fully Supporting	Remainder of reservoir	39,095	239		36.6
Chloride	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	239		36.6
Chloride	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	239		36.6
Chloride	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	239		36.6
Chloride	Fully Supporting	West Carolina Creek cove, off upper portion of reservoir	675	239		36.6
Sulfate	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146	237		52.5
Sulfate	Fully Supporting	Lower portion of reservoir, East Willow Springs	5,120	237		52.5
Sulfate	Fully Supporting	Lower portion of reservoir, East Wolf Creek	5,120	237		52.5
Sulfate	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	237		52.5
Sulfate	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120	237		52.5
Sulfate	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	237		52.5
Sulfate	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	237		52.5
Sulfate	Fully Supporting	Remainder of reservoir	39,095	237		52.5
Sulfate	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	237		52.5
Sulfate	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	237		52.5
Sulfate	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	237		52.5
Sulfate	Fully Supporting	West Carolina Creek cove, off upper portion of reservoir	675	237		52.5
Total Dissolved Solids	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146	317		269.3
Total Dissolved Solids	Fully Supporting	Lower portion of reservoir, East Willow Springs	5,120	317		269.3
Total Dissolved Solids	Fully Supporting	Lower portion of reservoir, East Wolf Creek	5,120	317		269.3

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

General Use (continued)

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Total Dissolved Solids	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	317		269.3
Total Dissolved Solids	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120	317		269.3
Total Dissolved Solids	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	317		269.3
Total Dissolved Solids	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	317		269.3
Total Dissolved Solids	Fully Supporting	Remainder of reservoir	39,095	317		269.3
Total Dissolved Solids	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	317		269.3
Total Dissolved Solids	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	317		269.3
Total Dissolved Solids	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	317		269.3
Total Dissolved Solids	Fully Supporting	West Carolina Creek cove, off upper portion of reservoir	675	317		269.3
Overall General Use	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146			
Overall General Use	Fully Supporting	Lower portion of reservoir, East Willow Springs	5,120			
Overall General Use	Fully Supporting	Lower portion of reservoir, East Wolf Creek	5,120			
Overall General Use	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall General Use	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120			
Overall General Use	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120			
Overall General Use	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall General Use	Fully Supporting	Remainder of reservoir	39,095			
Overall General Use	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324			
Overall General Use	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799			
Overall General Use	Partially Supporting	Upper portion of reservoir, west of Carlisle	4,841			
Overall General Use	Fully Supporting	West Carolina Creek cove, off upper portion of reservoir	675			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Fish Consumption Use						
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Lower portion of reservoir, East Willow Springs	5,120			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Lower portion of reservoir, East Wolf Creek	5,120			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841			
Advisories and Closures Risk Assess.-No Advisory	Fully Supporting	West Carolina Creek cove, off upper portion of reservoir	675			
Human Health Criteria Chromium	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	12		1.33
Human Health Criteria Chromium	No Concern-Limited Data	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	9		1.44
Human Health Criteria Chromium	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	33		1.18
Human Health Criteria Chromium	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	33		1.21
Human Health Criteria Chromium	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	12		1.33
Human Health Criteria Lead	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	13		1.31

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Fish Consumption Use (continued)						
Human Health Criteria Lead	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	10		1.3
Human Health Criteria Lead	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	35		1.26
Human Health Criteria Lead	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	35		1.29
Human Health Criteria Lead	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	13		1.31
Human Health Criteria Metals	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	36		
Overall Fish Consumption Use	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Fish Consumption Use	Fully Supporting	Lower portion of reservoir, East Willow Springs	5,120			
Overall Fish Consumption Use	Fully Supporting	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Fish Consumption Use	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Fish Consumption Use	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120			
Overall Fish Consumption Use	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120			
Overall Fish Consumption Use	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall Fish Consumption Use	Not Assessed	Remainder of reservoir	39,095			
Overall Fish Consumption Use	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324			
Overall Fish Consumption Use	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799			
Overall Fish Consumption Use	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841			
Overall Fish Consumption Use	Fully Supporting	West Carolina Creek cove, off upper portion of reservoir	675			
Public Water Supply Use						
Finished Water: Running Avg	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146			
Finished Water: Running Avg	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120			
Finished Water: Running Avg	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120			
Finished Water: Running Avg	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Public Water Supply Use (continued)						
Finished Water: Running Avg	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Finished Water: Running Avg	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324			
Finished Water: Running Avg	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799			
Finished Water: Running Avg	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841			
Surface Water: Long-term average Fluoride	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	29		0.49
Surface Water: Long-term average Fluoride	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	16		0.66
Surface Water: Long-term average Fluoride	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	16		0.57
Surface Water: Long-term average Nitrate+Nitrite Nitrogen	No Concern-Limited Data	Cove off upper portion of reservoir, East Trinity	4,146	8		0.48
Surface Water: Long-term average Nitrate+Nitrite Nitrogen	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120	52		0.22
Surface Water: Long-term average Nitrate+Nitrite Nitrogen	No Concern-Limited Data	Middle portion of reservoir, East Pointblank	5,120	9		0.37
Surface Water: Long-term average Nitrate+Nitrite Nitrogen	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120	11		0.47
Surface Water: Long-term average Nitrate+Nitrite Nitrogen	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	19		0.21
Surface Water: Long-term average Nitrate+Nitrite Nitrogen	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324	44		2.4
Surface Water: Long-term average Nitrate+Nitrite Nitrogen	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799	51		2.28
Surface Water: Long-term average Nitrate+Nitrite Nitrogen	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841	20		1.22
Overall Public Water Supply Use	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Public Water Supply Use	Fully Supporting	Lower portion of reservoir, East Willow Springs	5,120			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Public Water Supply Use (continued)						
Overall Public Water Supply Use	Fully Supporting	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Public Water Supply Use	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Public Water Supply Use	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120			
Overall Public Water Supply Use	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120			
Overall Public Water Supply Use	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall Public Water Supply Use	Fully Supporting	Remainder of reservoir	39,095			
Overall Public Water Supply Use	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324			
Overall Public Water Supply Use	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799			
Overall Public Water Supply Use	Fully Supporting	Upper portion of reservoir, west of Carlisle	4,841			
Overall Public Water Supply Use	Fully Supporting	West Carolina Creek cove, off upper portion of reservoir	675			
Overall Use Support						
	Fully Supporting	Cove off upper portion of reservoir, East Trinity	4,146			
	Fully Supporting	Lower portion of reservoir, East Willow Springs	5,120			
	Fully Supporting	Lower portion of reservoir, East Wolf Creek	5,120			
	Fully Supporting	Lowermost portion of reservoir, adjacent to dam	5,120			
	Fully Supporting	Middle portion of reservoir, East Pointblank	5,120			
	Fully Supporting	Middle portion of reservoir, centering on US 190	5,120			
	Fully Supporting	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
	Fully Supporting	Remainder of reservoir	39,095			
	Fully Supporting	Riverine portion of reservoir, centering on SH 21	324			
	Fully Supporting	Upper portion of reservoir, centering on SH 19	2,799			
	Partially Supporting	Upper portion of reservoir, west of Carlisle	4,841			
	Fully Supporting	West Carolina Creek cove, off upper portion of reservoir	675			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Nutrient Enrichment Concern						
Ammonia Nitrogen	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146	8		
Ammonia Nitrogen	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120	64	1	
Ammonia Nitrogen	Not Assessed	Middle portion of reservoir, East Pointblank	5,120	9		
Ammonia Nitrogen	No Concern	Middle portion of reservoir, centering on US 190	5,120	15	1	
Ammonia Nitrogen	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	20	0	
Ammonia Nitrogen	No Concern	Riverine portion of reservoir, centering on SH 21	324	58	3	
Ammonia Nitrogen	No Concern	Upper portion of reservoir, centering on SH 19	2,799	65	2	
Ammonia Nitrogen	No Concern	Upper portion of reservoir, west of Carlisle	4,841	24	1	
Nitrite + Nitrate Nitrogen	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146	8		
Nitrite + Nitrate Nitrogen	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120	52	13	
Nitrite + Nitrate Nitrogen	Not Assessed	Middle portion of reservoir, East Pointblank	5,120	9		
Nitrite + Nitrate Nitrogen	Concern	Middle portion of reservoir, centering on US 190	5,120	11	5	
Nitrite + Nitrate Nitrogen	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	19	4	
Nitrite + Nitrate Nitrogen	Concern	Riverine portion of reservoir, centering on SH 21	324	44	32	
Nitrite + Nitrate Nitrogen	Concern	Upper portion of reservoir, centering on SH 19	2,799	51	38	
Nitrite + Nitrate Nitrogen	Concern	Upper portion of reservoir, west of Carlisle	4,841	20	16	
Orthophosphorus	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146	8		
Orthophosphorus	Concern	Lowermost portion of reservoir, adjacent to dam	5,120	53	23	
Orthophosphorus	Not Assessed	Middle portion of reservoir, East Pointblank	5,120	9		
Orthophosphorus	Concern	Middle portion of reservoir, centering on US 190	5,120	14	10	
Orthophosphorus	Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	19	11	
Orthophosphorus	Concern	Riverine portion of reservoir, centering on SH 21	324	48	45	
Orthophosphorus	Concern	Upper portion of reservoir, centering on SH 19	2,799	53	51	

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Nutrient Enrichment Concern (continued)						
Orthophosphorus	Concern	Upper portion of reservoir, west of Carlisle	4,841	22	19	
Total Phosphorus	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146	0		
Total Phosphorus	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120	45	10	
Total Phosphorus	Not Assessed	Middle portion of reservoir, East Pointblank	5,120	0		
Total Phosphorus	Concern	Middle portion of reservoir, centering on US 190	5,120	12	8	
Total Phosphorus	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	10	2	
Total Phosphorus	Concern	Riverine portion of reservoir, centering on SH 21	324	51	47	
Total Phosphorus	Concern	Upper portion of reservoir, centering on SH 19	2,799	50	42	
Total Phosphorus	Concern	Upper portion of reservoir, west of Carlisle	4,841	13	10	
Overall Nutrient Enrichment Concerns	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Nutrient Enrichment Concerns	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120			
Overall Nutrient Enrichment Concerns	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Nutrient Enrichment Concerns	Concern	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Nutrient Enrichment Concerns	Not Assessed	Middle portion of reservoir, East Pointblank	5,120			
Overall Nutrient Enrichment Concerns	Concern	Middle portion of reservoir, centering on US 190	5,120			
Overall Nutrient Enrichment Concerns	Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall Nutrient Enrichment Concerns	Not Assessed	Remainder of reservoir	39,095			
Overall Nutrient Enrichment Concerns	Concern	Riverine portion of reservoir, centering on SH 21	324			
Overall Nutrient Enrichment Concerns	Concern	Upper portion of reservoir, centering on SH 19	2,799			
Overall Nutrient Enrichment Concerns	Concern	Upper portion of reservoir, west of Carlisle	4,841			
Overall Nutrient Enrichment Concerns	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Algal Growth Concern						
Chlorophyll a	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146	0		
Chlorophyll a	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120			
Chlorophyll a	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120			
Chlorophyll a	Concern	Lowermost portion of reservoir, adjacent to dam	5,120	17	8	
Chlorophyll a	Not Assessed	Middle portion of reservoir, East Pointblank	5,120	0		
Chlorophyll a	Not Assessed	Middle portion of reservoir, centering on US 190	5,120	6	0	
Chlorophyll a	Not Assessed	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	5	0	
Chlorophyll a	Not Assessed	Remainder of reservoir	39,095			
Chlorophyll a	Not Assessed	Riverine portion of reservoir, centering on SH 21	324	9	0	
Chlorophyll a	Concern	Upper portion of reservoir, centering on SH 19	2,799	17	5	
Chlorophyll a	Not Assessed	Upper portion of reservoir, west of Carlisle	4,841	6	0	
Chlorophyll a	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675			
Sediment Contaminants Concern						
Overall Sediment Contaminant Concerns	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Sediment Contaminant Concerns	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120			
Overall Sediment Contaminant Concerns	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Sediment Contaminant Concerns	Not Assessed	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Sediment Contaminant Concerns	Not Assessed	Middle portion of reservoir, East Pointblank	5,120			
Overall Sediment Contaminant Concerns	Not Assessed	Middle portion of reservoir, centering on US 190	5,120			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Sediment Contaminants Concern (continued)						
Overall Sediment Contaminant Concerns	Not Assessed	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall Sediment Contaminant Concerns	Not Assessed	Remainder of reservoir	39,095			
Overall Sediment Contaminant Concerns	Not Assessed	Riverine portion of reservoir, centering on SH 21	324			
Overall Sediment Contaminant Concerns	Not Assessed	Upper portion of reservoir, centering on SH 19	2,799			
Overall Sediment Contaminant Concerns	Not Assessed	Upper portion of reservoir, west of Carlisle	4,841			
Overall Sediment Contaminant Concerns	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675			
Fish Tissue Contaminants Concern						
Overall Fish Tissue Contaminant Concerns	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Middle portion of reservoir, East Pointblank	5,120			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Middle portion of reservoir, centering on US 190	5,120			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Remainder of reservoir	39,095			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Fish Tissue Contaminants Concern (continued)						
Overall Fish Tissue Contaminant Concerns	Not Assessed	Riverine portion of reservoir, centering on SH 21	324			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Upper portion of reservoir, centering on SH 19	2,799			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Upper portion of reservoir, west of Carlisle	4,841			
Overall Fish Tissue Contaminant Concerns	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675			
Public Water Supply Concern						
Finished Water: Chloride	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
Finished Water: Chloride	No Concern	Lower portion of reservoir, East Willow Springs	5,120			
Finished Water: Chloride	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
Finished Water: Chloride	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120			
Finished Water: Chloride	No Concern	Middle portion of reservoir, East Pointblank	5,120			
Finished Water: Chloride	No Concern	Middle portion of reservoir, centering on US 190	5,120			
Finished Water: Chloride	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Finished Water: Chloride	No Concern	Remainder of reservoir	39,095			
Finished Water: Chloride	No Concern	Riverine portion of reservoir, centering on SH 21	324			
Finished Water: Chloride	No Concern	Upper portion of reservoir, centering on SH 19	2,799			
Finished Water: Chloride	No Concern	Upper portion of reservoir, west of Carlisle	4,841			
Finished Water: Chloride	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			
Finished Water: Sulfate	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
Finished Water: Sulfate	No Concern	Lower portion of reservoir, East Willow Springs	5,120			
Finished Water: Sulfate	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
Finished Water: Sulfate	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Public Water Supply Concern (continued)						
Finished Water: Sulfate	No Concern	Middle portion of reservoir, East Pointblank	5,120			
Finished Water: Sulfate	No Concern	Middle portion of reservoir, centering on US 190	5,120			
Finished Water: Sulfate	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Finished Water: Sulfate	No Concern	Remainder of reservoir	39,095			
Finished Water: Sulfate	No Concern	Riverine portion of reservoir, centering on SH 21	324			
Finished Water: Sulfate	No Concern	Upper portion of reservoir, centering on SH 19	2,799			
Finished Water: Sulfate	No Concern	Upper portion of reservoir, west of Carlisle	4,841			
Finished Water: Sulfate	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			
Finished Water: Total Dissolved Solids	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
Finished Water: Total Dissolved Solids	No Concern	Lower portion of reservoir, East Willow Springs	5,120			
Finished Water: Total Dissolved Solids	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
Finished Water: Total Dissolved Solids	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120			
Finished Water: Total Dissolved Solids	No Concern	Middle portion of reservoir, East Pointblank	5,120			
Finished Water: Total Dissolved Solids	No Concern	Middle portion of reservoir, centering on US 190	5,120			
Finished Water: Total Dissolved Solids	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Finished Water: Total Dissolved Solids	No Concern	Remainder of reservoir	39,095			
Finished Water: Total Dissolved Solids	No Concern	Riverine portion of reservoir, centering on SH 21	324			
Finished Water: Total Dissolved Solids	No Concern	Upper portion of reservoir, centering on SH 19	2,799			
Finished Water: Total Dissolved Solids	No Concern	Upper portion of reservoir, west of Carlisle	4,841			
Finished Water: Total Dissolved Solids	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			
Finished Water: MTBE	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
Finished Water: MTBE	No Concern	Lower portion of reservoir, East Willow Springs	5,120			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Public Water Supply Concern (continued)						
Finished Water: MTBE	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
Finished Water: MTBE	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120			
Finished Water: MTBE	No Concern	Middle portion of reservoir, East Pointblank	5,120			
Finished Water: MTBE	No Concern	Middle portion of reservoir, centering on US 190	5,120			
Finished Water: MTBE	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Finished Water: MTBE	No Concern	Remainder of reservoir	39,095			
Finished Water: MTBE	No Concern	Riverine portion of reservoir, centering on SH 21	324			
Finished Water: MTBE	No Concern	Upper portion of reservoir, centering on SH 19	2,799			
Finished Water: MTBE	No Concern	Upper portion of reservoir, west of Carlisle	4,841			
Finished Water: MTBE	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			
Finished Water: Perchlorate	Not Assessed	Cove off upper portion of reservoir, East Trinity	4,146			
Finished Water: Perchlorate	Not Assessed	Lower portion of reservoir, East Willow Springs	5,120			
Finished Water: Perchlorate	Not Assessed	Lower portion of reservoir, East Wolf Creek	5,120			
Finished Water: Perchlorate	Not Assessed	Lowermost portion of reservoir, adjacent to dam	5,120			
Finished Water: Perchlorate	Not Assessed	Middle portion of reservoir, East Pointblank	5,120			
Finished Water: Perchlorate	Not Assessed	Middle portion of reservoir, centering on US 190	5,120			
Finished Water: Perchlorate	Not Assessed	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Finished Water: Perchlorate	Not Assessed	Remainder of reservoir	39,095			
Finished Water: Perchlorate	Not Assessed	Riverine portion of reservoir, centering on SH 21	324			
Finished Water: Perchlorate	Not Assessed	Upper portion of reservoir, centering on SH 19	2,799			
Finished Water: Perchlorate	Not Assessed	Upper portion of reservoir, west of Carlisle	4,841			
Finished Water: Perchlorate	Not Assessed	West Carolina Creek cove, off upper portion of reservoir	675			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Public Water Supply Concern (continued)

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Finished Water: Overall	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
Finished Water: Overall	No Concern	Lower portion of reservoir, East Willow Springs	5,120			
Finished Water: Overall	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
Finished Water: Overall	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120			
Finished Water: Overall	No Concern	Middle portion of reservoir, East Pointblank	5,120			
Finished Water: Overall	No Concern	Middle portion of reservoir, centering on US 190	5,120			
Finished Water: Overall	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Finished Water: Overall	No Concern	Remainder of reservoir	39,095			
Finished Water: Overall	No Concern	Riverine portion of reservoir, centering on SH 21	324			
Finished Water: Overall	No Concern	Upper portion of reservoir, centering on SH 19	2,799			
Finished Water: Overall	No Concern	Upper portion of reservoir, west of Carlisle	4,841			
Finished Water: Overall	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			
Surface Water: Chloride	No Concern	Cove off upper portion of reservoir, East Trinity	4,146	239		36.6
Surface Water: Chloride	No Concern	Lower portion of reservoir, East Willow Springs	5,120	239		36.6
Surface Water: Chloride	No Concern	Lower portion of reservoir, East Wolf Creek	5,120	239		36.6
Surface Water: Chloride	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120	239		36.6
Surface Water: Chloride	No Concern	Middle portion of reservoir, East Pointblank	5,120	239		36.6
Surface Water: Chloride	No Concern	Middle portion of reservoir, centering on US 190	5,120	239		36.6
Surface Water: Chloride	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	239		36.6
Surface Water: Chloride	No Concern	Remainder of reservoir	39,095	239		36.6
Surface Water: Chloride	No Concern	Riverine portion of reservoir, centering on SH 21	324	239		36.6
Surface Water: Chloride	No Concern	Upper portion of reservoir, centering on SH 19	2,799	239		36.6
Surface Water: Chloride	No Concern	Upper portion of reservoir, west of Carlisle	4,841	239		36.6

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Public Water Supply Concern (continued)						
Surface Water: Chloride	No Concern	West Carolina Creek cove, off upper portion of reservoir	675	239		36.6
Surface Water: Sulfate	No Concern	Cove off upper portion of reservoir, East Trinity	4,146	237		52.5
Surface Water: Sulfate	No Concern	Lower portion of reservoir, East Willow Springs	5,120	237		52.5
Surface Water: Sulfate	No Concern	Lower portion of reservoir, East Wolf Creek	5,120	237		52.5
Surface Water: Sulfate	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120	237		52.5
Surface Water: Sulfate	No Concern	Middle portion of reservoir, East Pointblank	5,120	237		52.5
Surface Water: Sulfate	No Concern	Middle portion of reservoir, centering on US 190	5,120	237		52.5
Surface Water: Sulfate	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	237		52.5
Surface Water: Sulfate	No Concern	Remainder of reservoir	39,095	237		52.5
Surface Water: Sulfate	No Concern	Riverine portion of reservoir, centering on SH 21	324	237		52.5
Surface Water: Sulfate	No Concern	Upper portion of reservoir, centering on SH 19	2,799	237		52.5
Surface Water: Sulfate	No Concern	Upper portion of reservoir, west of Carlisle	4,841	237		52.5
Surface Water: Sulfate	No Concern	West Carolina Creek cove, off upper portion of reservoir	675	237		52.5
Surface Water: Total Dissolved Solids	No Concern	Cove off upper portion of reservoir, East Trinity	4,146	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Lower portion of reservoir, East Willow Springs	5,120	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Lower portion of reservoir, East Wolf Creek	5,120	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Middle portion of reservoir, East Pointblank	5,120	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Middle portion of reservoir, centering on US 190	5,120	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Remainder of reservoir	39,095	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Riverine portion of reservoir, centering on SH 21	324	317		269.3

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Public Water Supply Concern (continued)						
Surface Water: Total Dissolved Solids	No Concern	Upper portion of reservoir, centering on SH 19	2,799	317		269.3
Surface Water: Total Dissolved Solids	No Concern	Upper portion of reservoir, west of Carlisle	4,841	317		269.3
Surface Water: Total Dissolved Solids	No Concern	West Carolina Creek cove, off upper portion of reservoir	675	317		269.3
Surface Water: Overall	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
Surface Water: Overall	No Concern	Lower portion of reservoir, East Willow Springs	5,120			
Surface Water: Overall	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
Surface Water: Overall	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120			
Surface Water: Overall	No Concern	Middle portion of reservoir, East Pointblank	5,120			
Surface Water: Overall	No Concern	Middle portion of reservoir, centering on US 190	5,120			
Surface Water: Overall	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Surface Water: Overall	No Concern	Remainder of reservoir	39,095			
Surface Water: Overall	No Concern	Riverine portion of reservoir, centering on SH 21	324			
Surface Water: Overall	No Concern	Upper portion of reservoir, centering on SH 19	2,799			
Surface Water: Overall	No Concern	Upper portion of reservoir, west of Carlisle	4,841			
Surface Water: Overall	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			
Overall Public Water Supply Concerns	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Public Water Supply Concerns	No Concern	Lower portion of reservoir, East Willow Springs	5,120			
Overall Public Water Supply Concerns	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Public Water Supply Concerns	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Public Water Supply Concerns	No Concern	Middle portion of reservoir, East Pointblank	5,120			
Overall Public Water Supply Concerns	No Concern	Middle portion of reservoir, centering on US 190	5,120			
Overall Public Water Supply Concerns	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Public Water Supply Concern (continued)						
Overall Public Water Supply Concerns	No Concern	Remainder of reservoir	39,095			
Overall Public Water Supply Concerns	No Concern	Riverine portion of reservoir, centering on SH 21	324			
Overall Public Water Supply Concerns	No Concern	Upper portion of reservoir, centering on SH 19	2,799			
Overall Public Water Supply Concerns	No Concern	Upper portion of reservoir, west of Carlisle	4,841			
Overall Public Water Supply Concerns	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			
Narrative Criteria Concern						
Overall Narrative Criteria Concerns	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
Overall Narrative Criteria Concerns	No Concern	Lower portion of reservoir, East Willow Springs	5,120			
Overall Narrative Criteria Concerns	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
Overall Narrative Criteria Concerns	No Concern	Lowermost portion of reservoir, adjacent to dam	5,120			
Overall Narrative Criteria Concerns	No Concern	Middle portion of reservoir, East Pointblank	5,120			
Overall Narrative Criteria Concerns	No Concern	Middle portion of reservoir, centering on US 190	5,120			
Overall Narrative Criteria Concerns	No Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
Overall Narrative Criteria Concerns	No Concern	Remainder of reservoir	39,095			
Overall Narrative Criteria Concerns	No Concern	Riverine portion of reservoir, centering on SH 21	324			
Overall Narrative Criteria Concerns	No Concern	Upper portion of reservoir, centering on SH 19	2,799			
Overall Narrative Criteria Concerns	No Concern	Upper portion of reservoir, west of Carlisle	4,841			
Overall Narrative Criteria Concerns	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			
Overall Secondary Concern						
	No Concern	Cove off upper portion of reservoir, East Trinity	4,146			
	No Concern	Lower portion of reservoir, East Willow Springs	5,120			
	No Concern	Lower portion of reservoir, East Wolf Creek	5,120			
	Concern	Lowermost portion of reservoir, adjacent to dam	5,120			

Segment ID: 0803 **Water body name:** Lake Livingston

Reservoir | Trinity River Basin | Total size: 82,600 Acres

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Overall Secondary Concern (continued)						
	No Concern	Middle portion of reservoir, East Pointblank	5,120			
	Concern	Middle portion of reservoir, centering on US 190	5,120			
	Concern	Middle portion of reservoir, downstream of Kickapoo Creek	5,120			
	No Concern	Remainder of reservoir	39,095			
	Concern	Riverine portion of reservoir, centering on SH 21	324			
	Concern	Upper portion of reservoir, centering on SH 19	2,799			
	Concern	Upper portion of reservoir, west of Carlisle	4,841			
	No Concern	West Carolina Creek cove, off upper portion of reservoir	675			