Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Aquatic Life Use						
Dissolved Oxygen grab average	No Concern	From CR 117 crossing to the upper end of the segment	19	15	1	
Dissolved Oxygen grab average	No Concern	From the CR 5 crossing to the FM 1690 crossing	13	16	0	
Dissolved Oxygen grab average	No Concern	From the FM 1690 crossing to the CR 117 crossing	18	13	0	
Dissolved Oxygen grab average	No Concern	From the FM 2657 crossing to the CR 5 crossing	18	17	0	
Dissolved Oxygen grab average	No Concern	Lower 26 miles of the segment to the FM 2657 crossing	26	26	0	
Dissolved Oxygen grab minimum	Fully Supporting	From CR 117 crossing to the upper end of the segment	19	15	0	
Dissolved Oxygen grab minimum	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13	16	0	
Dissolved Oxygen grab minimum	Fully Supporting	From the FM 1690 crossing to the CR 117 crossing	18	13	0	
Dissolved Oxygen grab minimum	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18	17	0	
Dissolved Oxygen grab minimum	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26	26	0	
Dissolved Oxygen 24hr average	Not Assessed	From CR 117 crossing to the upper end of the segment	19	0		
Dissolved Oxygen 24hr average	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13	0		
Dissolved Oxygen 24hr average	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18	0		
Dissolved Oxygen 24hr average	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18	0		
Dissolved Oxygen 24hr average	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26	0		
Dissolved Oxygen 24hr minimum	Not Assessed	From CR 117 crossing to the upper end of the segment	19	0		
Dissolved Oxygen 24hr minimum	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13	0		
Dissolved Oxygen 24hr minimum	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18	0		
Dissolved Oxygen 24hr minimum	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18	0		

Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Aquatic Life Use (continued)						
Dissolved Oxygen 24hr minimum	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26	0		
Overall Aquatic Life Use	Fully Supporting	From CR 117 crossing to the upper end of the segment	19			
Overall Aquatic Life Use	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13			
Overall Aquatic Life Use	Fully Supporting	From the FM 1690 crossing to the CR 117 crossing	18			
Overall Aquatic Life Use	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18			
Overall Aquatic Life Use	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26			
Contact Recreation Use						
E. coli single sample	Not Assessed	From CR 117 crossing to the upper end of the segment	19	0		
E. coli single sample	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13	0		
E. coli single sample	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18	0		
E. coli single sample	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18	0		
E. coli single sample	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26	0		
E. coli geometric mean	Not Assessed	From CR 117 crossing to the upper end of the segment	19	0		
E. coli geometric mean	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13	0		
E. coli geometric mean	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18	0		
E. coli geometric mean	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18	0		
E. coli geometric mean	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26	0		
Fecal coliform single sample	Use Concern	From CR 117 crossing to the upper end of the segment	19	14	4	

Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Contact Recreation Use (continued)						
Fecal coliform single sample	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13	15	4	
Fecal coliform single sample	Not Supporting	From the FM 1690 crossing to the CR 117 crossing	18	12	6	
Fecal coliform single sample	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18	15	3	
Fecal coliform single sample	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26	27	5	
Fecal coliform geometric mean	Fully Supporting	From CR 117 crossing to the upper end of the segment	19	14		172
Fecal coliform geometric mean	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13	15		137.8
Fecal coliform geometric mean	Not Supporting	From the FM 1690 crossing to the CR 117 crossing	18	12		235.1
Fecal coliform geometric mean	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18	15		134.1
Fecal coliform geometric mean	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26	27		106.3
Overall Recreation Use	Fully Supporting	From CR 117 crossing to the upper end of the segment	19			
Overall Recreation Use	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13			
Overall Recreation Use	Not Supporting	From the FM 1690 crossing to the CR 117 crossing	18			
Overall Recreation Use	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18			
Overall Recreation Use	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26			
General Use						
Water Temperature	Fully Supporting	From CR 117 crossing to the upper end of the segment	19	15	0	
Water Temperature	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13	16	0	
Water Temperature	Fully Supporting	From the FM 1690 crossing to the CR 117 crossing	18	13	0	
Water Temperature	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18	20	0	
Water Temperature	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26	27	0	

Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
General Use (continued)						
pH	Fully Supporting	From CR 117 crossing to the upper end of the segment	19	15	0	
pH	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13	16	0	
pH	Fully Supporting	From the FM 1690 crossing to the CR 117 crossing	18	13	0	
pH	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18	17	0	
pH	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26	26	0	
Chloride	Fully Supporting	From CR 117 crossing to the upper end of the segment	19	81		101.7
Chloride	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13	81		101.7
Chloride	Fully Supporting	From the FM 1690 crossing to the CR 117 crossing	18	81		101.7
Chloride	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18	81		101.7
Chloride	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26	81		101.7
Sulfate	Fully Supporting	From CR 117 crossing to the upper end of the segment	19	80		34.1
Sulfate	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13	80		34.1
Sulfate	Fully Supporting	From the FM 1690 crossing to the CR 117 crossing	18	80		34.1
Sulfate	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18	80		34.1
Sulfate	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26	80		34.1
Total Dissolved Solids	Fully Supporting	From CR 117 crossing to the upper end of the segment	19	97		553.1
Total Dissolved Solids	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13	97		553.1
Total Dissolved Solids	Fully Supporting	From the FM 1690 crossing to the CR 117 crossing	18	97		553.1
Total Dissolved Solids	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18	97		553.1

Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
General Use (continued)						
Total Dissolved Solids	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26	97		553.1
Overall General Use	Fully Supporting	From CR 117 crossing to the upper end of the segment	19			
Overall General Use	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13			
Overall General Use	Fully Supporting	From the FM 1690 crossing to the CR 117 crossing	18			
Overall General Use	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18			
Overall General Use	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26			
Fish Consumption Use						
Overall Fish Consumption Use	Not Assessed	From CR 117 crossing to the upper end of the segment	19			
Overall Fish Consumption Use	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13			
Overall Fish Consumption Use	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18			
Overall Fish Consumption Use	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18			
Overall Fish Consumption Use	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26			
Overall Use Support						
	Fully Supporting	From CR 117 crossing to the upper end of the segment	19			
	Fully Supporting	From the CR 5 crossing to the FM 1690 crossing	13			
	Not Supporting	From the FM 1690 crossing to the CR 117 crossing	18			
	Fully Supporting	From the FM 2657 crossing to the CR 5 crossing	18			
	Fully Supporting	Lower 26 miles of the segment to the FM 2657 crossing	26			

Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Nutrient Enrichment Concern						
Ammonia Nitrogen	Not Assessed	From CR 117 crossing to the upper end of the segment	19	0		
Ammonia Nitrogen	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13	0		
Ammonia Nitrogen	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18	0		
Ammonia Nitrogen	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18	4	0	
Ammonia Nitrogen	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26	2	0	
Nitrite + Nitrate Nitrogen	No Concern	From CR 117 crossing to the upper end of the segment	19	15	0	
Nitrite + Nitrate Nitrogen	No Concern	From the CR 5 crossing to the FM 1690 crossing	13	15	0	
Nitrite + Nitrate Nitrogen	No Concern	From the FM 1690 crossing to the CR 117 crossing	18	13	0	
Nitrite + Nitrate Nitrogen	No Concern	From the FM 2657 crossing to the CR 5 crossing	18	19	0	
Nitrite + Nitrate Nitrogen	No Concern	Lower 26 miles of the segment to the FM 2657 crossing	26	23	0	
Orthophosphorus	No Concern	From CR 117 crossing to the upper end of the segment	19	15	0	
Orthophosphorus	No Concern	From the CR 5 crossing to the FM 1690 crossing	13	15	0	
Orthophosphorus	No Concern	From the FM 1690 crossing to the CR 117 crossing	18	13	0	
Orthophosphorus	No Concern	From the FM 2657 crossing to the CR 5 crossing	18	19	0	
Orthophosphorus	No Concern	Lower 26 miles of the segment to the FM 2657 crossing	26	23	1	
Total Phosphorus	Not Assessed	From CR 117 crossing to the upper end of the segment	19	0		
Total Phosphorus	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13	0		
Total Phosphorus	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18	0		
Total Phosphorus	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18	4	0	

Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Nutrient Enrichment Concern (continued)						
Total Phosphorus	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26	2	1	
Overall Nutrient Enrichment Concerns	No Concern	From CR 117 crossing to the upper end of the segment	19			
Overall Nutrient Enrichment Concerns	No Concern	From the CR 5 crossing to the FM 1690 crossing	13			
Overall Nutrient Enrichment Concerns	No Concern	From the FM 1690 crossing to the CR 117 crossing	18			
Overall Nutrient Enrichment Concerns	No Concern	From the FM 2657 crossing to the CR 5 crossing	18			
Overall Nutrient Enrichment Concerns	No Concern	Lower 26 miles of the segment to the FM 2657 crossing	26			
Algal Growth Concern						
Chlorophyll a	Not Assessed	From CR 117 crossing to the upper end of the segment	19	0		
Chlorophyll a	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13	0		
Chlorophyll a	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18	0		
Chlorophyll a	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18	4	0	
Chlorophyll a	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26	2	0	
Sediment Contaminants Concern						
Overall Sediment Contaminant Concerns	Not Assessed	From CR 117 crossing to the upper end of the segment	19			
Overall Sediment Contaminant Concerns	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13			
Overall Sediment Contaminant Concerns	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18			
Overall Sediment Contaminant Concerns	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18			

Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Sediment Contaminants Concern (continued)						
Overall Sediment Contaminant Concerns	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26			
Fish Tissue Contaminants Concern						
Overall Fish Tissue Contaminant Concerns	Not Assessed	From CR 117 crossing to the upper end of the segment	19			
Overall Fish Tissue Contaminant Concerns	Not Assessed	From the CR 5 crossing to the FM 1690 crossing	13			
Overall Fish Tissue Contaminant Concerns	Not Assessed	From the FM 1690 crossing to the CR 117 crossing	18			
Overall Fish Tissue Contaminant Concerns	Not Assessed	From the FM 2657 crossing to the CR 5 crossing	18			
Overall Fish Tissue Contaminant Concerns	Not Assessed	Lower 26 miles of the segment to the FM 2657 crossing	26			
Narrative Criteria Concern						
Overall Narrative Criteria Concerns	No Concern	From CR 117 crossing to the upper end of the segment	19			
Overall Narrative Criteria Concerns	No Concern	From the CR 5 crossing to the FM 1690 crossing	13			
Overall Narrative Criteria Concerns	No Concern	From the FM 1690 crossing to the CR 117 crossing	18			
Overall Narrative Criteria Concerns	No Concern	From the FM 2657 crossing to the CR 5 crossing	18			
Overall Narrative Criteria Concerns	No Concern	Lower 26 miles of the segment to the FM 2657 crossing	26			
Overall Secondary Concern						
	No Concern	From CR 117 crossing to the upper end of the segment	19			
	No Concern	From the CR 5 crossing to the FM 1690 crossing	13			
	No Concern	From the FM 1690 crossing to the CR 117 crossing	18			
	No Concern	From the FM 2657 crossing to the CR 5 crossing	18			

Segment ID: 1217 **Water body name:** Lampasas River Above Stillhouse Hollow Lake

Freshwater Stream | Brazos River Basin | Total size: 94 Miles

Assessment Method	Status of Use Support or Concern	Location	Location size	# of samples	# of exceedances	Mean
Overall Secondary Concern (continued)						
	No Concern	Lower 26 miles of the segment to the FM 2657 crossing	26			